Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

 1242
 DWECK RESIDENCE
 NY Spills
 \$110488212

 NNE
 40 COLIN PLACE
 N/A

> 1 1.606 mi. 8478 ft. BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 DWECK RESIDENCE

 Actual:
 Address:
 40 COLIN PLACE

 24 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 1002377 / Not Reported

 Facility ID:
 1002377

 Facility Type:
 ER

 DER Facility ID:
 390409

 Site ID:
 435508

 DEC Region:
 2

Spill Cause: Unknown Spill Class: Not reported SWIS: 2401 2010-06-01 Spill Date: Investigator: **RMPIPER** Referred To: Not reported Reported to Dept: 2010-06-01 CID: Not reported Water Affected: Not reported Private Dwelling Spill Source:

Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:
Last Inspection:
Recommended Penalty:
UST Trust:
Remediation Phase:

Other
Not reported
False
False
False
1

Date Entered In Computer: 2010-06-01
Spill Record Last Update: 2017-03-03
Spiller Name: ALEX CASTRO
Spiller Company: UNKNOWN
Spiller Address: 36 COLIN PLACE

Spiller Company: 999

Contact Name: ALEX CASTRO

DEC Memo: "06/02/10-Vought-Primary off-hours responder. Vought called and spoke

to NYCDEP Alex Castro (Cell:347-865-1238) and he received call from DEC investigator of spill. Spill is 10 wide area of contaminated soil around a heating oil fill port in a sidewalk between 36 Colin Place and 40 Colin Place. Castro was not sure which residence was owner of the fill port and the possible UST. The fill port was approximately 1.5' away from 40 Colin Place and 4' away from 36 Coline Place. Castro spoke to the owner of 36 Colin Place (who wished to remain anonymous but noted odors from the contaminted soil) and he said that he converted to gas when he bought the home years ago. The owner of 36 Colin Place also noted that for the past ten years he observed no spill at the fill port and it just appeared recently. As per Castro he knocked on the door of 40 Colin Place, a woman answered and when

he knocked on the door of 40 Colin Place, a woman answered and when he stated he was from DEP regarding the spill, no one opened the door and no further response was received from the occupants. Vought checked PBS and Spills and no listings found for 36 or 40 Colin Place. DEC Piper to perform site visit as he will be in neighborhood on 6/3/10. Owner info as per ACRIS: Erica Dweck (husband is Nathan) 40 Colin Place Brooklyn, NY 11223 and Alex Missry 36 Colin Place

Brooklyn, NY 11223 06/03/10-Vought-Spoke with DEC Piper who performed

Map ID MAP FINDINGS
Direction

Distance Elevation S

Site EDR ID Number EPA ID Number EPA ID Number

site visit this morning and spoke with Erica Dweck and noted that she should hire contractor to properly abandon UST (may be a 550 or 1000 gallon tank). Dweck agreed that she would hire contractor to abandon UST. Vought sent CSL out as per Piper with 30 month deadline to Dweck at address above and assigned spill to Piper as he performed site visit and impending transfer of Vought to Section A. 8-4-11- Info request sent.2nd attempt 03-03-2017- Info request sent.3rd attempt"

"Caller reporting that he found oil seeping up from the ground

inbetween 2 residences. Unknown source."

All Materials:

Remarks:

Site ID: 435508 Operable Unit ID: 1186270 Operable Unit: 01 Material ID: 2181051 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: Not reported Units:

Recovered: Not reported Oxygenate: Not reported